

**GOVERNMENT OF INDIA  
MINISTRY OF RAILWAYS  
RAILWAY BOARD.**

XXR/FAX/POST COPY  
NEW DELHI, DATED 24 -01-2011

THE GENERAL MANAGERS,  
ALL INDIAN RAILWAYS.

---

NO.2011/SAFETY-I/3/1 (.) YARD DERAILMENT OF LOCO OF A LOADED BCN RAKE TOOK PLACE WHILE PLACEMENT AT JAMUI YARD OF EAST CENTRAL RAILWAY ON 23.01.2011 AT CROSS OVER POINT BLOCKING UP AND DOWN MAINLINE (.) TO PREVENT RECURRENCE OF SIMILAR INCIDENTS, ~~DRIVE~~ DRIVE MAY BE LAUNCHED TO ENSURE PROPER MAINTENANCE AND UPKEEP OF CROSS OVER POINTS CONNECTING MAINLINES ON RAJDHANI, SHATABDI AND DURONTO ROUTES (.) SOMETIMES, REGULAR MAINTENANCE IS POSTPONED IN ANTICIPATION OF IMPENDING YARD REMODELLING, RRI, PI WORKS, ETC. (.) THIS TENDENCY IS TO BE AVOIDED (.) A JOINT CERTIFICATE REGARDING TESTING AND OPERATION OF CROSS OVER POINTS CONNECTING MAINLINE SIGNED BY SUPERVISORS OF S&T AND P. WAY SHOULD BE AVAILABLE IN THE CONTROL OFFICE WITHIN THE NEXT ONE MONTH (.) COMPLIANCE REPORT ON THE ABOVE MAY BE FURNISHED TO THE BOARD (.)

**ADVISER (SAFETY), RAILWAY BOARD**

---



(SUNIL KUMAR)  
Adviser (Safety), Railway Board.

Copy to : Chief Safety Officers, All Indian Railways for information and n/a